



## Mines Safety Bulletin No. 184

**Subject:** Workers ejected from underground work platform

**Date:** 30 August 2021

### Background

In July 2020, a service crew at an underground mine was hanging an electrical trailing cable for a jumbo drill in an ore drive, when two workers were tipped out of a work platform (WP) attached to an integrated tool carrier (ITC).

As the two workers were hanging the cable from the WP, a hydraulic failure associated with the tilt cylinder (crowd function) on the boom of the ITC caused the WP to tilt fully forward under gravity. Due to the sudden and unexpected movement, one of the workers was ejected from the WP onto the ground below while the other remained in the WP as his right boot was caught in the door.

The hydraulic failure resulted from the anti-dump valve on the tilt cylinder becoming separated from the cylinder port when its mounting bolts sheared. The mounting bolts sheared when the body of the anti-dump valve clashed with the lifting frame of the ITC as the boom was being raised.

The floor of the WP was reported to be approximately two metres off the ground immediately prior to the incident, and despite both workers wearing fall control equipment, their shock adsorbing lanyards failed to deploy. Although the two workers received minor physical injuries, the potential consequences could have been much more serious.



Work platform on integrated tool carrier at location of the July 2020 incident (scene preserved following rescue of injured persons).

## Summary of hazard

For persons working within a WP there is risk of exposure to fall from height hazards due to the following potential causes:

- machine components failing (e.g. WP detaching from quick hitch, dog-bone failure, hydraulic failure)
- machine overturning (e.g. from operating the machine beyond its load and stability limits, uneven ground conditions)
- persons being ejected from the WP due to the "catapult effect" (e.g. wheels contact an obstacle or depression when tramming with persons in the WP)
- machine driving over an edge (e.g. unbunded open stope).

The July 2020 incident was the third in a recent series of serious and potentially serious events relating to WP and ITC combinations used underground at different mine sites. These incidents were:


- March 2018: WP detached from quick hitch and fell to ground – one worker injured
- February 2020: dog-bone failure – two workers injured when they were ejected from an underground WP
- July 2020: anti-dump valve failure – two workers injured when they were ejected from an underground WP.

## Contributory factors

In the case of the July 2020 incident, there were a number of key contributory factors involved.

- The anti-dump valve fitted to the tilt cylinder had been retrofitted to the ITC by a previous owner. It was neither a standard nor an optional feature provided by the original equipment manufacturer (OEM), but an after-market retrofit. The OEM manuals available to maintenance personnel contained no information regarding this device or how it should be installed, tested and commissioned.
- The anti-dump valve included no guard or cover to protect it from physical impact. Other ITCs in the same fleet had robust protective covers on their anti-dump valves.
- The anti-dump valve involved in the incident required an adapter block for mounting. The adapter block made the "anti-dump valve" more vulnerable to impacts and allowed mounting in two different orientations. One of the available orientations did not allow clearance for the full range of boom elevation. These issues were not known to maintenance personnel and there were no mounting, testing or commissioning instructions available to them. A correctly sized anti-dump valve should match the hydraulic port size and mounting holes on the hydraulic cylinder so it can be directly mounted.
- After the anti-dump valve had been fitted to the tilt cylinder, the tilt capability was function tested, but the boom lift had not been function tested through the full range of movement. The anti-dump valve only clashed with the lifting frame of the ITC when the boom was raised close to full height during subsequent operational use.
- The WP and ITC combination was functionally a Type 2, Group B vehicle mounted mobile elevating work platform (MEWP). However, it was not fully compliant with AS1418.10:2011 and was not being managed as registered classified plant. Furthermore, because the equipment was essentially being managed as earthmoving equipment rather than as an MEWP, the periodic inspection requirements of AS 2550.1 were not being followed.

- Although both workers were wearing fall arrest harnesses with standard 1.5-metre long shock absorbing lanyards attached to fall arrest anchor points on the front of the basket, the WP was not being used at sufficient height for the fall prevention system to stop the users from impacting the ground. No inertia reel type devices were used. A combination of shorter lanyards, alternate anchor points and/or inertia reel devices may have provided better protection.



Anti-dump valve on clevis end of tilt cylinder - re-enactment showing how valve body will clash with lifting frame of ITC.

## Actions required

The load-holding cylinders on MEWPs are required to be fitted with a safety device to prevent unintended movement caused by failure of a hydraulic line (refer to AS1418.10, Section 2.9.2). On an ITC with a WP that is used underground, this is typically achieved by fitting what is referred to as an "anti-dump valve" or "hose burst protection" to each of the boom lift and tilt cylinders. Such safety devices should:

- always be installed, tested, inspected and maintained in accordance with the ITC's original equipment manufacturer (OEM) instructions. When non-OEM supplied devices are used or other changes are made to the OEM design, appropriate change management and engineering due diligence must be applied
- be designed, selected, installed, tested, periodically inspected and maintained by competent persons to ensure they have a high level of reliability
- whenever they are fitted or replaced, have a complete functionality test of the ITC's physical movements and hydraulic functions performed, all in accordance with OEM recommendations before the ITC is returned to service.

The following is also recommended to prevent similar reoccurrence:

- Competent service and maintenance personnel should be provided with ready access to adequate procedures, OEM guidance, instructions and information – reliance on the knowledge and experience of maintenance workers alone, however reliable and competent they may be, may not always prove to be a safe system of work.

- For safety critical items, any repair, replacement, modification or test work should be checked or witnessed by a second competent person or supervisor before the machine is returned to service – reliance on the work of a single maintenance worker, however reliable and competent they may be, may not always prove to be a safe system of work.
- An ITC operated with a WP is effectively a powered hoist designed to lift people, and therefore needs to be managed as classified plant – unless exempted, compliance with AS/NZS 1418.10 is required.
- If an ITC can lift people more than 2.4 metres, then it needs to be of an approved (registered) design and be managed by the mine as registered classified plant – the periodic inspection requirements of AS 2550.1 should apply.
- Persons working within a WP should use an appropriate fall control system (i.e. combination of fall arrest and/or fall restraint equipment) which is designed to prevent the user impacting the ground as a result of any reasonably foreseeable fall from height event – any potential free-fall should be limited to less than 600 mm (refer AS/NZS 1891.4).
- The carriage of loose items and persons together within a WP should be avoided – tools and materials carried in the WP should be adequately secured so that they cannot become hazardous projectiles or falling objects as a result of any foreseeable event.

## Further information

Further guidance may be found in the following:

- Mines Safety and Inspection Regulations, 1994 – Part 6.

Department of Mines, Industry Regulation and Safety

- MSB No. 114 *Compliance requirements for multi-purpose mobile plant*  
[www.dmp.wa.gov.au/Documents/Safety/SRS-Publications-Mining\\_and\\_Explorations-Safety\\_Bulletin\\_114.pdf](http://www.dmp.wa.gov.au/Documents/Safety/SRS-Publications-Mining_and_Explorations-Safety_Bulletin_114.pdf)

Standards Australia

- AS/NZS 1891.4:2009 Industrial fall arrest systems and devices - Part 4: Selection, use and maintenance.
- AS/NZS 1418.10:2011 Cranes hoists and winches - Part 10: Mobile elevating work platforms.
- AS 2550.1-2002 Cranes, hoists and winches - Safe use - Part 1: General requirements.

Visit [www.dmirs.wa.gov.au/ResourcesSafety](http://www.dmirs.wa.gov.au/ResourcesSafety) for information on occupational safety and health in the resources sector.

This Mines Safety Bulletin was approved for release by the State Mining Engineer on 30 August 2021