


3 RISK CONTROL MEASURES

- Separation of LP Gas from dwellings, workshops, offices
- Segregation of LP Gas from incompatible dangerous goods and fuel storage
- Protection provided to prevent vehicular impact on tanks and fittings
- Adoption of safe transfer procedures
- Exclusion of ignition sources in vicinity of tanks, cylinders and decant points
- Control of explosive gas atmospheres – ventilation and electrical equipment rating
- Control of fire hazards – removal of adjacent combustible material



[www.dmp.wa.gov.au/
ResourcesSafety](http://www.dmp.wa.gov.au/ResourcesSafety)

4 EMERGENCY PLANNING MEASURES

- Emergency plan adopted and rehearsed with staff and contractors
- Appropriate fire fighting equipment
- Training of staff in contingency measures