

Government of Western Australia Department of Mines and Petroleum Resources Safety

Petroleum Safety Significant Incident Report No. 06/2013

Collapse of mobile lighting tower results in equipment damage

Summary of incident

At the beginning of a work-over operation on an oil well, a mobile lighting tower was erected to provide light during night activities. A few days later, the tower fell onto the lighting plant generator, damaging the equipment. Fortunately, no-one was in the vicinity of the tower when it fell or the outcome could have been more serious.

Contributory factors

- The mast was not perfectly aligned during installation, and therefore the spring-loaded locking pin only partially engaged.
- No instruction manual or written procedure for deployment was available.

Preventative actions

Mobile lighting towers are used throughout the resources sector, but are probably not included as a potential hazard when risk assessing a job requiring illumination. However, towers typically range from 7 to 12 metres in height when fully extended, and can weigh hundreds of kilograms. Therefore they can represent a significant falling object hazard if the tower is not properly secured.

To help control this hazard:

- provide workers with adequate information, such as manuals and procedures, to ensure installations are performed correctly
- implement routine double-checks (preferably independent) for plant installations (e.g. another worker to confirm that all locking mechanisms are fully engaged in lighting towers).

Borh

Alan Gooch DIRECTOR PETROLEUM SAFETY 10 December 2013