
Summary Data

MRF tenement activities for July 2017 – June 2018 period


Released under section 15(3) of the Mining Rehabilitation Fund Act 2012

| | Disturbance (ha) | Land Under Rehabilitation (ha) |
|------------------------|---------------------|--------------------------------------|
| Exploration Licences | 10,514 | 32 |
| General Purpose Leases | 3,139 | 1,093 |
| Miscellaneous Licences | 12,881 | 952 |
| Mining Leases | 98,677 | 36,482 |
| Prospecting Licences | 603 | 67 |
| Retention Licences | 383 | 0 |
| Total | 126,197 | 38,627 |


(based on data as at 17 September 2018)




Total Disturbance




Land Under Rehabilitation



Disturbance Land



Disturbance (ha)



Land Under Rehabilitation (ha)

| Mining Activity Type | Disturbance (ha) | Land Under Rehabilitation (ha) |
|---|---------------------|--------------------------------------|
| Airstrip | 1,693 | 213 |
| Basic raw material extraction - processing equipment or stockpile associated with basic raw material extraction | 600 | 42 |
| Borefield | 1,616 | 26 |
| Borrow pit or shallow surface excavation (with a depth of less than 5 metres) | 2,434 | 1,737 |
| Building (other than workshop) or camp site | 1,347 | 241 |
| Core yard | 175 | 3 |
| Dam - fresh water | 490 | 38 |
| Dam - saline water or process liquor | 570 | 16 |
| Diversion channel or drain | 1,158 | 159 |
| Evaporation pond | 1,279 | 188 |
| Exploration/prospecting operations - land (other than land under rehabilitation or rehabilitated land) that has been disturbed by exploration operations | 21,925 | - |
| Fuel storage facility | 56 | 17 |
| Heap or vat leach facility | 583 | 215 |
| Landfill site | 181 | 47 |
| Laydown or hardstand area | 5,666 | 3,049 |
| Low-grade ore stockpile (class 1) | 1,122 | 109 |
| Low-grade ore stockpile (class 2) | 1,727 | 257 |
| Mining void (with a depth of at least 5 metres) - above ground water level | 6,125 | 1,848 |
| Mining void (with a depth of at least 5 metres) - below ground water level | 9,218 | 5,276 |
| Other cleared land - land (other than land under rehabiliation or rehabiliated land) that is cleared of vegetation and is not otherwise described in thibable | 5,497 | - |
| Plant site | 1,439 | 229 |
| Run-of-mine pad | 3,604 | 468 |
| Sewage pond | 133 | 8 |
| Tailings or residue storage facility (class 1) | 13,121 | 2,866 |
| Tailings or residue storage facility (class 2) | 1,903 | 1,119 |
| Topsoil stockpile | 4,176 | 921 |
| Transport or service infrastructure corridor | 23,061 | 1,691 |
| Waste dump or overburden stockpile (class 1) | 12,681 | 14,497 |
| Waste dump or overburden stockpile (class 2) | 2,258 | 3,305 |
| Workshop | 357 | 41 |
| Total | 126,197 | 38,627 |

(based on data as at 17 September 2018)

| Mining Activity Type (Simplified) | Disturbance (ha) | Land Under Rehabilitation (ha) |
|--|---------------------|--------------------------------------|
| Airstrip | 1,693 | 213 |
| Basic raw material extraction | 600 | 42 |
| Borefield | 1,616 | 26 |
| Borrow pit or shallow surface excavation (< 5 m) | 2,434 | 1,737 |
| Building or camp site | 1,347 | 241 |
| Core yard | 175 | 3 |
| Dam - fresh water | 490 | 38 |
| Dam - saline water or process liquor | 570 | 16 |
| Diversion channel or drain | 1,158 | 159 |
| Evaporation pond | 1,279 | 188 |
| Exploration/prospecting operations | 21,925 | - |
| Fuel storage facility | 56 | 17 |
| Heap or vat leach facility | 583 | 215 |
| Landfill site | 181 | 47 |
| Laydown or hardstand area | 5,666 | 3,049 |
| Low-grade ore stockpile | 2,849 | 366 |
| Mining void (> 5 m) | 15,344 | 7,124 |
| Other cleared land | 5,497 | - |
| Plant site | 1,439 | 229 |
| Run-of-mine pad | 3,604 | 468 |
| Sewage pond | 133 | 8 |
| Tailings or residue storage facility | 15,024 | 3,985 |
| Topsoil stockpile | 4,176 | 921 |
| Transport or service infrastructure corridor | 23,061 | 1,691 |
| Waste dump or overburden stockpile | 14,939 | 17,803 |
| Workshop | 357 | 41 |
| Total | 126,197 | 38,627 |

(based on data as at 17 September 2018)

Note: This information is collected solely for the purposes of calculating the levy, and should be used with caution when drawing conclusions, particularly about trends in mining and rehabilitation activity. Additionally, it should be noted that:

- the Rehabilitation Liability Estimate (derived by applying the category unit rates to the reported areas of activity) is a
 'normalised' base for deriving levies across activities and does not necessarily correlate in any way to 'real' rehabilitation costs
 at any one site.
- the reported area (in hectares) is a 'snapshot in time' that can be assessed by tenement holders at any point in the year.
- changes in disturbance and rehabilitation levels from one reporting period to the next may be comparing data that was not assessed at the same point in time (e.g. they could be at assessed by the holder on 30 June in Year 1 and on 1 July in Year 2) and/or may not show the impact of increases and decreases that occur within the reporting period.
- the data does not include disturbance and rehabilitation attributable to operators under a State Agreement. It therefore reflects only a sub-set of mining activity across the State and is unlikely to be indicative of the industry as a whole.